

US EPA ARCHIVE DOCUMENT

Appendix A.1. - Monitoring Well Conditions Reports



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-3 Date: 7/10/2013

Access:
 Accessibility: Good Fair Poor
 Vicinity of well clear of weeds and/or debris: Yes No
 Remarks: Cleared weed & for well on 7/10/2013

Concrete Pad:
 Any issues with concrete pad? No Yes If yes, then explain below.
 Presence of depressions or standing water around well: Yes No
 Remarks: N/A

Protective Outer Casing: Material: Steel
 Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>


 Remarks: N/A

Well Riser: Material: PVC
 Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

 Remarks: N/A

Dedicated Purging / Sampling Device Present?
 Yes No If yes, what type of device? Water foot valve & tubing
 Condition: Good Damaged If Damaged, please provide written description.
 Remarks: N/A

Field Certification:  Signed Sonia Chemical Engineer Title 7/10/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-6 Date: 7/12/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared branches from well on 7/12/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad buried if present - excavate pad will cause water to pond around well

Protective Outer Casing:

Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser:

Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Western Foot Valve & tube

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:

[Signature]
Signed

[Signature]
Title

7/12/2013
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-12 Date: 7/15/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Waterria
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/15/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-13 Date: 7/18/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Watererra Tubing
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: [Signature] Managing Director 7/18/13
Signed Title Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-14 Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>
Condition of Locking Cap:	Good <input type="checkbox"/>	Damaged <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>

Remarks: Locking cap hinge broken - unable to repair due to presence of landfill gas which is a spark hazard. Unable to drill weep hole for same reason.

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterro foot valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:

Signed

Senior Chemical Engineer Title

7/10/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-01 Date: 7/17/2013

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared weeds from well on 7/17/2013

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Watercote Foot Valve, etc
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: [Signature] Signed Title Senior Control Engineer Date 7/17/2013

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-93 Date: 7/11/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Walking access only

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad buried if present - excavating pad will cause water to pond around well

Protective Outer Casing: Material: _____

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: No exterior ID - well ID written on PVC riser cap

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: NIA

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Watera foot valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: NIA

Field Certification: [Signature] Signed _____ Title Senior Chemical Engineer Date 7/11/2013

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-85 Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Concrete blocks in front of well

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing:

Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser:

Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Water foot valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:

[Signature]
Signed

Senior General Engineer
Title

7/10/2013
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-87 Date: 7/17/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterira

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/17/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: D-93 Date: 7/11/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Working access only - cleared weeds from well on 7/11/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall foot valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:  Signed Senior Chemical Engineer Title 7/11/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: <u>West Lake Landfill</u>	Well ID: <u>I-4</u>	Date: <u>7/10/2013</u>	
Access:			
Accessibility:	Good <input type="checkbox"/>	Fair <input checked="" type="checkbox"/>	Poor <input type="checkbox"/>
Vicinity of well clear of weeds and/or debris:	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	
Remarks: <u>Cleared weeds from well on 7/10/2013</u>			
Concrete Pad:			
Any issues with concrete pad?	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	If yes, then explain below.
Presence of depressions or standing water around well:	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	
Remarks: <u>N/A</u>			
Protective Outer Casing: Material: <u>Steel</u>			
Note: For ANY indication of Damaged, please provide written description			
Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Remarks: <u>N/A</u>			
Well Riser: Material: <u>Pvc</u>			
Note: For ANY indication of Damaged, please provide written description			
Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Remarks: <u>N/A</u>			
Dedicated Purging / Sampling Device Present?			
Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	If yes, what type of device? <u>Waterz foot valve & tubing</u>	
Condition:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	If Damaged, please provide written description.
Remarks: <u>N/A</u>			

Field Certification: [Signature] Senior Control Engineer 7/10/2013
 Signed Title Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: I-9 Date: 7/11/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Walking access only - Cleared weeds from well on 7/11/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing:

Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser:

Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall Foot valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature]

Signed

[Signature]

Title

7/11/2013

Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: I-11 Date: 7/15/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Waterma
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/15/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: I-62 Date: 7/12/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: walking access only

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing:

Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: Well ID written on PVC riser cap.

Well Riser:

Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:

[Signature]
Signed

Senior Chemical Engineer
Title

7/12/2013
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: I-65 Date: 7/15/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Walking access only - cleared weeds from well on 7/10/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/> [Ⓟ]
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>

Remarks: Well ID written on PVC riser cap and on top of steel csg.

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall foot valve & tube

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior-Chemical Engineer Title 7/15/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: I-66 Date: 7/15/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: Pad Duried if Present

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Watera
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/15/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: J-68 Date: 7/12/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Water Werra Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/12/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: I-73 Date: 7/18/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Water Tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Managing Director 7/18/13
 Signed Title Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: LR-100 Date: 7/17/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared Weeds Around Well

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Waterira
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/17/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: LR-103 Date: 7/17/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared Weeds Around Well

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: Pad Buried if Present

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Water
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/17/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: LR-104 Date: 7/22/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds from well on 7/10/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: Removed large weep nests from well on 7/10/2013 + 7/22/2013

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Water table valve & pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/22/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: LR-105 Date: 7/17/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Waterira
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/17/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: NW-102 Date: 7/15/2013

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared weeds from well on 7/12/2013

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: Pad buried, if present - excavating pad will cause water to pond around well.

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: Well ID written on PVC riser cap

Well Riser: Material: PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? N/A
Condition: Good N/A Damaged N/A If Damaged, please provide written description.
Remarks: N/A

Field Certification:  Signed _____ Title Senior Remedial Engineer Date 7/15/2013

US EPA ARCHIVE DOCUMENT



GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: MW-103 Date: 7/15/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared tall grass from well on 7/18/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: NIA

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: NIA

Well Riser: Material: PU

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: NIA

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? NIA

Condition: Good NIA Damaged NIA If Damaged, please provide written description.

Remarks: NIA

Field Certification: [Signature]
Signed

Semi-Chemical Engineer
Title

7/15/2013
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: MW-104 Date: 7/16/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: Pad Buried if Present

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: Drilled weep hole on 7/16/13

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Waterco
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/16/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: MW-1204 Date: 7/11/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds Around well

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2 -inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/11/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-100-K5 Date: 7/22/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? N/A

Condition: Good N/A Damaged N/A If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior Licensed Engineer Title 7/22/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-100-50 Date: 7/9/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/9/13
 Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-100-SS Date: 7/9/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/9/13
 Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-101-SS Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared grass from well on 7/10/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad buried, if present; excavating pad will cause water to pond around well

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>


Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall valve & tube

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:  Signed Senior Chemist/Engineer Title 7/10/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PE-102R-55 Date: 7/12/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds for well on 7/18/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad buried, if present excavating pad will cause water to pond around well

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall foot valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior Remedial Engineer Title 7/12/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-102-SS Date: 7/12/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Clear tall grass from well on 7/18/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad buried, if present. excavating pad will cause water to pond around well

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Watera Foot valve & tap

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior Remediation Engineer Title 7/12/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-103-55 Date: 7/16/13

Access:
 Accessibility: Good Fair Poor
 Vicinity of well clear of weeds and/or debris: Yes No
 Remarks: N/A

Concrete Pad:
 Any issues with concrete pad? No Yes If yes, then explain below.
 Presence of depressions or standing water around well: Yes No
 Remarks: N/A

Protective Outer Casing: Material: steel
 Note: For ANY indication of Damaged, please provide written description
 Condition of Protective Casing: Good Damaged Missing
 Condition of Exterior Well ID Markings: Good Damaged Missing
 Condition of Locking Cap: Good Damaged Missing
 Condition of Lock: Good Damaged Missing
 Condition of Weep Hole: Good Damaged Missing
 Remarks: N/A

Well Riser: Material: 2-inch pvc
 Note: For ANY indication of Damaged, please provide written description
 Condition of Riser: Good Damaged
 Condition of Riser Cap: Good Damaged Missing
 Measurement Reference Point: Good Damaged Missing
 Remarks: N/A

Dedicated Purging / Sampling Device Present?
 Yes No If yes, what type of device? Watera
 Condition: Good Damaged If Damaged, please provide written description.
 Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/16/13
 Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-104KS Date: 7/18/2013

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: _____

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: Pad is under HDPE liner

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? N/A
Condition: Good N/A Damaged N/A If Damaged, please provide written description.
Remarks: N/A

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/18/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-104-SD Date: 7/11/13

Access:
Accessibility: Good X Fair Poor
Vicinity of well clear of weeds and/or debris: Yes X No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No X Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No X
Remarks: Well surrounded by HDPE liner.

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good X Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing X
Condition of Locking Cap: Good X Damaged Missing
Condition of Lock: Good X Damaged Missing
Condition of Weep Hole: Good X Damaged Missing
Remarks: Added Exterior well ID on 7/11/13

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good X Damaged
Condition of Riser Cap: Good X Damaged Missing
Measurement Reference Point: Good X Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes X No If yes, what type of device? Bladder Pump
Condition: Good X Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/11/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-104-55 Date: 7/11/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: well surrounded by HDPE liner

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2 inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Signed Matt Stewart Project Geologist Title 7/11/13 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-105-SJ Date: 7/12/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Well surrounded by HDPE liner.

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Bladder Pump
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/12/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-10645 Date: 7/19/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Weeds all around site

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: dirt completely covering pad area, could not see

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? N/A
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: [Signature] Env. Specialist 7/19/13
Signed Title Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-106-SD Date: 7/10/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared Weeds Around Well

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Signed Project Geologist Title 7/10/13 Date

Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-106-SS Date: 7/10/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared Weeds Around well

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Bladder Pump
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/10/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-107-SS Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds on 7/10/2013.

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad is exposed underneath but still solid.

Protective Outer Casing:

Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser:

Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall flow valve & pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:

[Signature]
Signed

Senior Counsel Agree
Title

7/10/2013
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-109-SS Date: 7/10/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Bladder Pump
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/10/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-110-S5 Date: 7/9/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Well Surrounded by Baker tanks; Clear path to well

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/9/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-~~111~~10KS Date: 7/17/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: NIA

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: NIA

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: NIA

Well Riser: Material: PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: NIA

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? NIA
Condition: Good NIA Damaged NIA If Damaged, please provide written description.
Remarks: NIA

Field Certification: [Signature] Env. Specialist 7/27/13
Signed Title Date
ERIC Herst

US EPA ARCHIVE DOCUMENT



GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-III-50 Date: 7/9/12

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing:

Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser:

Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: _____

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:

Matt Stewart
Signed
Matt Stewart

Project Geologist
Title

7/9/12
Date

US EPA ARCHIVE DOCUMENT



GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-U2-A5 Date: 7/9/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: NIA

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: NIA

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: NIA

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: NIA

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall foot valve + tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: NIA

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/9/2013 Date

US EPA ARCHIVE DOCUMENT



GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-113-AD Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: NIA

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: NIA

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: NIA

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: NIA

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Underfoot valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: NIA

Field Certification: [Signature]
Signed

Senior Chemical Engineer
Title

7/10/2013
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-113-AS Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: NIA

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: NIA

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: NIA

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: NIA

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: NIA

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/10/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-113-55 Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: NIA

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: NIA

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: NIA

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: NIA

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Water fast valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: NIA

Field Certification: [Signature]
Signed

Semi-Chemical Engineer
Title

7/10/2013
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-114-AS Date: 7/12/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: _____

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Bladder Pump
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/12/13
Signed: Matt Stewart Title: _____ Date: _____

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-115-SS Date: 7/11/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/11/13
 Signed Matt Stewart Title Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-116-55 Date: 7/11/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared Weeds Around Well

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Bladder Pump
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/11/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-200-SS Date: 7/19/12

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Watera

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/19/12
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-201A-SS Date: 7/10/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/10/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-202-55 Date: 7/11/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared Weeds + shrubs around well

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Bladder Pump
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/11/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-203-SS Date: 7/17/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad lowered, if present - excavating pad will cause water to pond around well

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: Well ID written inside on PVC after cap - added exterior ID on 7/17/2013

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? water foot valve 1/2" b/g

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Semo, Chemical Engineer Title 7/17/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-20YA-53 Date: 7/16/2011

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel + concrete

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>

Remarks: Flush mount well - no weep hole needed

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>


Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall Foot Valve & Tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification:  Signed _____ Title Senior Chemical Engineer Date 7/16/2011

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PE-204-SS Date: 7/16/2013

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: Steel + Concrete
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: Flush mount well - no weep hole needed

Well Riser: Material: PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Waterz foot valve & tubing
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/16/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-205-AS Date: 7/18/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Waterria
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/18/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-205-55 Date: 7/10/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Bladder Pump

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/10/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-206-SJ Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Concrete plant foundation ongoing during time of security

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall Foot Valve, 1' tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed _____ Title Senior Client Engineer Date 7/10/2013

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-207-AS Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds from well on 7/10/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser: Material: DUC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfoot valve & filter

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature]
Signed

Senior Chemical Engineer
Title

7/10/2013
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-208-SS Date: 7/15/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: N/A

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? N/A
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/15/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-302-AI Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds from well on 7/10/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Uterera foot valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior Process Engineer Title 7/10/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: PZ-302-AS Date: 7/16/2013

Access:
 Accessibility: Good Fair Poor
 Vicinity of well clear of weeds and/or debris: Yes No
 Remarks: Cleared weeds from well on 7/10/2013

Concrete Pad:
 Any issues with concrete pad? No Yes If yes, then explain below.
 Presence of depressions or standing water around well: Yes No
 Remarks: N/A

Protective Outer Casing: Material: Steel
 Note: For ANY indication of Damaged, please provide written description
 Condition of Protective Casing: Good Damaged Missing
 Condition of Exterior Well ID Markings: Good Damaged Missing
 Condition of Locking Cap: Good Damaged Missing
 Condition of Lock: Good Damaged Missing
 Condition of Weep Hole: Good Damaged Missing
 Remarks: N/A

Well Riser: Material: PVC
 Note: For ANY indication of Damaged, please provide written description
 Condition of Riser: Good Damaged
 Condition of Riser Cap: Good Damaged Missing
 Measurement Reference Point: Good Damaged Missing
 Remarks: N/A

Dedicated Purging / Sampling Device Present?
 Yes No If yes, what type of device? N/A
 Condition: Good N/A Damaged N/A If Damaged, please provide written description.
 Remarks: N/A

Field Certification: [Signature] Signed [Signature] Title Senior Landfill Engineer Date 7/16/2013

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-303-A5 Date: 7/15/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Walking access only - Cleared weeds from well on 7/10/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? N/A

Condition: Good N/A Damaged N/A If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior Licensed Engineer Title 7/15/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-304-AI Date: 7/16/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared weeds Around well

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Watera
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/16/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P2-304-As Date: 7/16/13

Access:
Accessibility: Good Fair Poor
Vicinity of well clear of weeds and/or debris: Yes No
Remarks: Cleared weeds Around well

Concrete Pad:
Any issues with concrete pad? No Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes No
Remarks: N/A

Protective Outer Casing: Material: steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged Missing
Condition of Exterior Well ID Markings: Good Damaged Missing
Condition of Locking Cap: Good Damaged Missing
Condition of Lock: Good Damaged Missing
Condition of Weep Hole: Good Damaged Missing
Remarks: N/A

Well Riser: Material: 2-inch pvc
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged
Condition of Riser Cap: Good Damaged Missing
Measurement Reference Point: Good Damaged Missing
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No If yes, what type of device? Waterca
Condition: Good Damaged If Damaged, please provide written description.
Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/16/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: P7-305-A2 Date: 7/22/2011

Access:
Accessibility: Good _____ Fair Poor _____
Vicinity of well clear of weeds and/or debris: Yes _____ No
Remarks: Cleared weeds from well on 7/10/2013.

Concrete Pad:
Any issues with concrete pad? No _____ Yes If yes, then explain below.
Presence of depressions or standing water around well: Yes _____ No
Remarks: Pad buried, if present - excavating pad will cause water to pond around well

Protective Outer Casing: Material: Steel
Note: For ANY indication of Damaged, please provide written description
Condition of Protective Casing: Good Damaged _____ Missing _____
Condition of Exterior Well ID Markings: Good Damaged _____ Missing _____
Condition of Locking Cap: Good Damaged _____ Missing _____
Condition of Lock: Good Damaged _____ Missing _____
Condition of Weep Hole: Good _____ Damaged _____ Missing
Remarks: Removed weep hole from steel csg on 7/18/2013 ; 7/22/2013

Well Riser: Material: PVC
Note: For ANY indication of Damaged, please provide written description
Condition of Riser: Good Damaged _____
Condition of Riser Cap: Good Damaged _____ Missing _____
Measurement Reference Point: Good Damaged _____ Missing _____
Remarks: N/A

Dedicated Purging / Sampling Device Present?
Yes No _____ If yes, what type of device? Waterfall valve ; flow
Condition: Good Damaged _____ If Damaged, please provide written description.
Remarks: N/A

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/22/2011 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: S-5 Date: 7/10/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds from well on 7/10/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterz fast valve & tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/10/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: <u>West Lake Landfill</u>	Well ID: <u>S-8</u>	Date: <u>7/12/2013</u>																				
Access: Accessibility: Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Vicinity of well clear of weeds and/or debris: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Remarks: <u>NIA</u>																						
Concrete Pad: Any issues with concrete pad? No <input checked="" type="checkbox"/> Yes <input type="checkbox"/> If yes, then explain below. Presence of depressions or standing water around well: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Remarks: <u>NIA</u>																						
Protective Outer Casing: Material: <u>Steel</u> Note: For ANY indication of Damaged, please provide written description <table style="width:100%; border:none;"> <tr> <td style="width:35%;">Condition of Protective Casing:</td> <td style="width:15%;">Good <input checked="" type="checkbox"/></td> <td style="width:15%;">Damaged <input type="checkbox"/></td> <td style="width:15%;">Missing <input type="checkbox"/></td> </tr> <tr> <td>Condition of Exterior Well ID Markings:</td> <td>Good <input type="checkbox"/></td> <td>Damaged <input type="checkbox"/></td> <td>Missing <input checked="" type="checkbox"/></td> </tr> <tr> <td>Condition of Locking Cap:</td> <td>Good <input checked="" type="checkbox"/></td> <td>Damaged <input type="checkbox"/></td> <td>Missing <input type="checkbox"/></td> </tr> <tr> <td>Condition of Lock</td> <td>Good <input checked="" type="checkbox"/></td> <td>Damaged <input type="checkbox"/></td> <td>Missing <input type="checkbox"/></td> </tr> <tr> <td>Condition of Weep Hole:</td> <td>Good <input type="checkbox"/></td> <td>Damaged <input type="checkbox"/></td> <td>Missing <input checked="" type="checkbox"/></td> </tr> </table> Remarks: <u>Well ID MARK on PVC riser cap</u>			Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>	Condition of Exterior Well ID Markings:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>	Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>	Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>	Condition of Weep Hole:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>
Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>																			
Condition of Exterior Well ID Markings:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>																			
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>																			
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>																			
Condition of Weep Hole:	Good <input type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>																			
Well Riser: Material: <u>PVC</u> Note: For ANY indication of Damaged, please provide written description <table style="width:100%; border:none;"> <tr> <td style="width:35%;">Condition of Riser:</td> <td style="width:15%;">Good <input checked="" type="checkbox"/></td> <td style="width:15%;">Damaged <input type="checkbox"/></td> <td style="width:15%;"></td> </tr> <tr> <td>Condition of Riser Cap:</td> <td>Good <input checked="" type="checkbox"/></td> <td>Damaged <input type="checkbox"/></td> <td>Missing <input type="checkbox"/></td> </tr> <tr> <td>Measurement Reference Point:</td> <td>Good <input checked="" type="checkbox"/></td> <td>Damaged <input type="checkbox"/></td> <td>Missing <input type="checkbox"/></td> </tr> </table> Remarks: <u>NIA</u>			Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>		Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>	Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>								
Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>																				
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>																			
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>																			
Dedicated Purging / Sampling Device Present? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> If yes, what type of device? <u>waterfoot valve & tubing</u> Condition: Good <input checked="" type="checkbox"/> Damaged <input type="checkbox"/> If Damaged, please provide written description. Remarks: <u>NIA</u>																						

Field Certification: Signed _____ Title Senior Remediation Officer Date 7/12/2013

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: S-10 Date: 7/15/13

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: N/A

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: N/A

Protective Outer Casing: Material: steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Exterior Well ID Markings:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Locking Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Lock	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>
Condition of Weep Hole:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>	Missing <input type="checkbox"/>

Remarks: N/A

Well Riser: Material: 2-inch pvc

Note: For ANY indication of Damaged, please provide written description

Condition of Riser:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/>
Condition of Riser Cap:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>
Measurement Reference Point:	Good <input checked="" type="checkbox"/>	Damaged <input type="checkbox"/> Missing <input type="checkbox"/>

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterira

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: Matt Stewart Project Geologist 7/15/13
Signed Title Date
Matt Stewart

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: S-53 Date: 7/18/2012

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds from well on 7/10/12

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad buried, if present - excavating pad will cause water to pond around well

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? N/A

Condition: Good N/A Damaged N/A If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature]
Signed

Senior Award Office
Title

7/18/12
Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: S-61 Date: 7/12/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Cleared weeds from well on 7/12/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: Pad buried, if present - well immediately inside fence - accessible by cutout for top of riser.

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: N/A

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: N/A

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Underground foot valve tubing

Condition: Good Damaged If Damaged, please provide written description.

Remarks: N/A

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/12/2013 Date

US EPA ARCHIVE DOCUMENT



HERST & ASSOCIATES, INC.®

Global Presence
Personal Attention

GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: S-02 Date: 7/11/2013

Access:

Accessibility: Good Fair Poor

Vicinity of well clear of weeds and/or debris: Yes No

Remarks: Walking access only - cleared weeds from well on 7/11/2013

Concrete Pad:

Any issues with concrete pad? No Yes If yes, then explain below.

Presence of depressions or standing water around well: Yes No

Remarks: NIA

Protective Outer Casing: Material: Steel

Note: For ANY indication of Damaged, please provide written description

Condition of Protective Casing: Good Damaged Missing

Condition of Exterior Well ID Markings: Good Damaged Missing

Condition of Locking Cap: Good Damaged Missing

Condition of Lock: Good Damaged Missing

Condition of Weep Hole: Good Damaged Missing

Remarks: NIA

Well Riser: Material: PVC

Note: For ANY indication of Damaged, please provide written description

Condition of Riser: Good Damaged

Condition of Riser Cap: Good Damaged Missing

Measurement Reference Point: Good Damaged Missing

Remarks: NIA

Dedicated Purging / Sampling Device Present?

Yes No If yes, what type of device? Waterfall valve & trans

Condition: Good Damaged If Damaged, please provide written description.

Remarks: NIA

Field Certification: [Signature]
Signed

Senior Chemical Engineer
Title

7/11/2013
Date

US EPA ARCHIVE DOCUMENT



GROUND WATER MONITORING WELL CONDITION REPORT

Facility: West Lake Landfill Well ID: S-B4 Date: 7/10/2013

Access:
 Accessibility: Good Fair Poor
 Vicinity of well clear of weeds and/or debris: Yes No
 Remarks: Concrete blocks in front of well

Concrete Pad:
 Any issues with concrete pad? No Yes If yes, then explain below.
 Presence of depressions or standing water around well: Yes No
 Remarks: NIA

Protective Outer Casing: Material: Steel
 Note: For ANY indication of Damaged, please provide written description
 Condition of Protective Casing: Good Damaged Missing
 Condition of Exterior Well ID Markings: Good Damaged Missing
 Condition of Locking Cap: Good Damaged Missing
 Condition of Lock: Good Damaged Missing
 Condition of Weep Hole: Good Damaged Missing
 Remarks: NIA

Well Riser: Material: PVC
 Note: For ANY indication of Damaged, please provide written description
 Condition of Riser: Good Damaged
 Condition of Riser Cap: Good Damaged Missing
 Measurement Reference Point: Good Damaged Missing
 Remarks: NIA

Dedicated Purging / Sampling Device Present?
 Yes No If yes, what type of device? Watermeter foot valve & tubing
 Condition: Good Damaged If Damaged, please provide written description.
 Remarks: NIA

Field Certification: [Signature] Signed Senior Chemical Engineer Title 7/10/2013 Date

US EPA ARCHIVE DOCUMENT